Q-285

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.fleet.ford.com/truckbbas (click "Contact Us")

Toll-free: (877) 840-4338

QVM Bulletin: Q-285 Date: 21, February 2018

2018 Super Duty Aftermarket CHSML Access

Models Affected: 2018 Model Year Super Duty Pickups and Chassis Cabs

Description: Starting 2018 Model Year, a CHMSL feed is provided at the end of frame for all Super Duty vehicles (see figure 1). This is a 5 amp fuse protected feed.

Wire Color	Circuit No.	Circuit Intent	Description
Violet	CBP04	Service Brake signal output	**6.7L Diesel, 6.2L / 6.8L Gas – BCM Pin C2280G-7**
			Intended for upfitter added CHMSL. BCM fuse F4, 5 Amp – Blunt cut taped to harness at rear of frame on left hand side



Figures 1: CHMSL feed location at end of frame

Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the Ford Truck Body Builders Advisory Service as shown in the header of this bulletin.